



Cascade Engineering Services, Inc.

# X-Ray and Electron Probing Applications


Reliability Engineering Group  
Cascade Engineering Services, Inc.  
6640 185th Ave NE Redmond WA 98052  
(425) 895-8617 x 564

[www.cascade-eng.com](http://www.cascade-eng.com)


# Capacitor Failure Investigation

## Equipment Used


- Dye and Pry Technique



Capacitor: 3D X-Ray Image



3D X-Ray: Open Terminal observed



X-section Optical Image


## Conclusions

- Separation of terminal from the electrode as the failure site confirmed
- 3D X-Ray helped identify the cross-section site for further failure investigation


# PCBA Open Trace Failure Investigation

## Equipment Used

- 3D X-Ray followed by X-section / SEM



Capacitor: 3D X-Ray Image, cross section view



3D X-Ray: Open Terminal observed

## Conclusions




- Cracks observed in both vias from X-Ray imaging confirmed by SEM
- 3D X-Ray helped identify the cross-section site for further failure investigation

# PCBA BGA Solder Joint Delamination




## Equipment Used

- 3D X-Ray followed by X-section / SEM

## 3D X-Ray Images



## SEM Images



## Conclusions


- Solder joints delamination on the chip side observed in 3D X-Ray and confirmed by SEM Imaging

# PCBA BGA Solder Joint Delamination


## Equipment Used

- 3D X-Ray followed by X-section / SEM


3D X-Ray Image



SEM Image



Crack observed in 3D X-Ray imaging and confirmed by SEM imaging




# Manufacturing Defect in a Cable Connector Assembly


## Equipment Used

- 3D X-Ray followed by X-section / SEM

3D X-Ray Images



SEM Images



## Conclusions

- Insufficient soldering observed in the 3D X-Ray imaging and confirmed by SEM imaging
- Combination of techniques: useful tool for quality / inspection applications


# Low Power Transceiver Failure Analysis

## Equipment Used


- 3D X-Ray followed by X-section / SEM

## Failure Mode

- 3-pt Mechanical Bend Test



3D X-Ray Image



SEM Image after x-section

## Conclusions

- Overstress failure resulting in delamination at multiple interfaces (PCBA-Bond Pad and Solder-Bond Pad)
- Obvious failures-eliminating the need for one of the tools either SEM or X-Ray depending on destructive or non-destructive technique


# Network Interface Card Failure Analysis

## Equipment Used


- 3D X-Ray followed by X-section / SEM

## Failure Mode

- Mechanical Overstress Test



3D X-Ray Image



SEM Image after x-section

## Conclusions


- Overstress failure resulting in delamination at multiple interfaces (PCBA-Bond Pad and Solder-Bond Pad)
- Obvious failures-eliminating the need for one of the tools either SEM or X-Ray depending on destructive or non-destructive technique




# Quality Inspection of a Cell Phone Cable Connector

## Equipment Used

- 3D X-Ray followed by X-section / SEM



3D X-Ray Image



SEM Image after x-section

## Conclusions

- Bridging of joints – highlighting the importance of 3D X-Ray as a quick and effective inspection tool


# Cell Phone PCBA CPU Failure Analysis

## Equipment Used


- 3D X-Ray followed by X-section / SEM

## Failure Mode

- Mechanical Bend Test



3D X-Ray Image



SEM Image after x-section

## Conclusions

- Overstress failure resulting in delamination at multiple interfaces (PCBA-Bond Pad and Solder-Bond Pad)
- Failure confirmation from X-Ray eliminates the need for SEM if non-destructive technique is called for


# Cell Phone PCBA CPU Failure Analysis

## Equipment Used


- 3D X-Ray followed by X-section / SEM

## Failure Mode

- Mechanical Bend Test



3D X-Ray Image



SEM Image after x-section